



RADIOGRAPHIC EXAMINATION REPORT


Acuren Inspection, Inc.
21112 South Scott Park Road
Davenport, Iowa 52807
Phone: 563.391.8500

www.acuren.com
A Higher Level of Reliability

Report Number: DAV413381

CUSTOMER: Akron Services
LOCATION/ADDRESS: 17705 N. Elevator Rd., Edelstein, Illinois
PART # / DRAWING #: Tank #88
ITEM DESCRIPTION: Anhydrous Ammonia Nurse Tank

Table with columns: NDE PROCEDURE, REV., SPECIFICATION/CODE, REV./EDITION, ACCEPTANCE PROCEDURE / STANDARD, PARTS INSPECTED, ACCEPTED, REJECTED. Includes material details like Carbon Steel, 238 in. diameter.



SOURCE: Ir, Co, Se, X-Ray
Ci 88, kv N/A, ma N/A
DENSITOMETER MODEL #: X-RITE 301
DENSITOMETER SERIAL #: 023361
CAL. DUE DATE: 06/05/2024

Table with columns: Weld/Component, View, Technique, Density, Accept/Reject, List Indications, Welder ID - Other ID Remarks. Shows results for Weld #2 and Back Head.

Additional Pages, Comments, Per Diem, Assistant Tech Name, # of Film & Size, Total # of Welds, No. on Job, Travel if Applicable, Hours Worked, Total Hours.

CLIENT REPRESENTATIVE, ACUREN INSPECTOR Patrick A. Ritter, Date 06/11/2024, Inspection Level II.

The Client Representative who receives this report is responsible for verifying that the acceptance standard listed in the report is correct, confirming that all radiographs listed in the report have been received by Client and promptly notifying Acuren of any issues with this report and/or the work summarized herein.

This document and all services and/or products provided in connection with this document and all future sales are subject to and shall be governed by the 'Acuren Standard Service Terms' in effect when the services and/or products are ordered.