



BRUNA IMPLEMENT COMPANY

12 East North Street
Seneca, KS 66538

Voice: 1-785-336-2111 FAX: 1-785-336-2035



SOLD TO
NEM10F NEMAHA CO COOP
PO BOX 204
SENECA, KS 66538

SHIP TO

Sold By: DK PO #: 13X111 AUGER SN: 190351 HR .0 W:00 C:
Ship By: Tax #: 00480350130F01 Date 9/09/15 WORK ORDERS WF10091
16:25:51 PRT: 2

Tax	D	Qty	Description	Price	Amount	
NOTES						
New lower section auger & new auger from hopper to boot.						
PRTS SHOP MISC						
N		1	1 1/4 X 1 1/2 KEY STOCK	.98	.98	
SHOP LABOR						
					** TOTAL SHOP LABOR	1464.00
PARTS SHOP CASE						
N		1	MIS WF17030 LOWER FLIGH	931.60	931.60	
N		1	MIS WF18932 AUGER	841.23	841.23	
N		1	HYC TOOLBOXBUDDY PENETRATE O	6.82	6.82	
N		1	MIS 12X48 GR8 BOLT	1.80	1.80	
N		1	MIS 716X1128 GR8 BOLT	.38	.38	
N		1	MIS 12LN 1/2 LOCKNUT	.36	.36	
N		1	MIS 716LN 7/16 LOCKNU	.31	.31	
N		10	MIS 58X4128 GR8 BOLT	3.73	37.30	
N		2	MIS WF18518 1-3/4 BRG 4	108.16	216.32	
N		20	MIS 58LN 5/8 LOCKNUT	.78	15.60	
N		1	MIS WF17371 WASHER 13"	5.40	5.40	
N		1	MIS WF17522 WHEEL ASSY	68.37	68.37	
					** TOTAL PARTS SHOP CASE	2125.49
FREIGHT						
N			FREIGHT		44.73	

Removed hopper and lift auger. Separated lift auger from hopper. Pulled old flighting out of lift auger tube. Removed hydraulic drive system. Put new flighting in. Washed the gearbox in the lift auger tube. There was oil on the outside of it, but couldn't find a leak. Checked oil level. It was full.

Removed pto shaft and drive sprocket. Removed bottom auger bearing and took the boot off. Had to cut the bearing off the shaft. Took loose the upper end of flighting and removed old bearing. Pulled the flighting out of the auger tube. Found a few loose nuts on the bolts holding the flightings together. Also found the rest of the flighting questionable. Called Brian and he come up to look it over. One flighting was 2 weeks out and we decided to install the bad flighting and reuse the rest. Will need replaced before next season. Replaced all bolts that connect the augers and double lock nutted them. Slid the flighting back in the tubes and installed the lower boot.

PRINT _____





BRUNA IMPLEMENT COMPANY

12 East North Street
Seneca, KS 66538

Voice: 1-785-336-2111 FAX: 1-785-336-2035



SOLD TO NEM10F NEMAHA CO COOP
PO BOX 204
SENECA, KS 66538

SHIP TO

Sold By: DK PO #: 13X111 AUGER Date 9/09/15 HR 0 W:00 C: WORK ORDERS WF10091
Ship By: Tax #: 00480350130F01 16:25:51 PRT: 2

Tax D Qty Description Price Amount

Installed new bearings top & bottom. Installed drive sprocket and chain.
Installed the pto shaft and put th elift auger back on and attached the
hopper.
Replaced one of the wheels on the hopper that was bad.
Installed the hydraulic drive and greased auger and hopper.

Upper bearing was dry and needs to be greased daily just like the lower
bearing.

This copy is for your records. You will receive a bill from CNH Capitol.
Thank you for your business.

Transaction ID: 01Z6DQK50100P65AEE22082B0HL2U2UG
Client ID: 3337786003
Store ID: 1393085006

Remit to:
Regular Mail: Productivity Plus P.O. Box 688912 Des Moines, IA 50368-8912
Express Mail: Productivity Plus 4740 121st St Urbandale, IA 50323

By signing I certify that I am authorized to use this Account, to
sign this receipt, and that I agree that the total amount of this
invoice is repayable in accordance with the Credit Agreement
applicable to the Account.

** SUBTOTAL 3635.20

PRINT _____

X _____ CC XXXXXXXXXXXXX4407 AUTH#